



M10 Lag screws must have 90mm penetration into double joist