

(1) Fix angle and seal to sides of box. At sides and base, *claddings* shall overlap angle by 10mm minimum. Continuously seal *cladding* against angle.

