


Installation

If arm supplied



Cleaning

Water contains lime which remains on the surface after the water has evaporated. These lime deposits can be prevented from forming by wiping dry immediately after use.

To clean the chrome plated surfaces use a soft cloth, soap and warm water. Never use cleaning agents that contain a corrosive acid or a scouring additive.



Cleaning





Do not use any sharp objects to clean nozzles.

For more cleaning instructions please visit www.satinjet.com